Version 2.0.0.03 Update (2010/02/01)

(1) In Transmitter Test 1A-07a, UITA issued FAIL result incorrectly in the following condition:

[Condition]

When a Source DUT accesses to HDCP port too fast too many times after HDCP port is disabled.

- UITA may issue the following ERROR during test period.

"[ET-18] ERROR: DUT did not access HDCP port at least once every 2 seconds'"

=====>

FIXED, BUG.